
Staithes Coastal Strategy

Appendix B

List of Reports Produced

This appendix contains a list of reports that have been produced that provide information of relevance to the Staithes Coastal Strategy.

These reports are available to view upon request to Scarborough Borough Council.

High Level Plans

- *Huntcliffe (Saltburn) to Flamborough Head (Sub-cell 1d) Shoreline Management Plan (1997)*
- *River Tyne to Flamborough Head Shoreline Management Plan 2 (2007) [Ref 183]*

Reports available from Scarborough Borough Council

- River Tyne to Flamborough Head Shoreline Management Plan 2 – 2007 [Ref 183]
- Cowbar Coast Protection and Cliff Stabilisation – June 1999 [Ref 36]
- Cowbar Coast Protection and Cliff Stabilisation (strategic Study) – December 1999 [Ref 37]
- Staithes Harbour Improvements and Cowbar Coast Protection & Cliff Stabilisation – September 2000 [Ref 87]
- Staithes Harbour Phase III Improvements – September 1999 [Ref 88]
- Staithes Urgent Harbour Wall Improvement PAR – May 2012 [Ref 316]
- Cowbar Nab Monitoring – August 2018 [Ref 392]
- Cowbar Nab Monitoring – April 2014 [Ref 393]
- Runswick Bay Rock pool specification and Survey Report 1 – February 2019 [Ref 396]
- Cell 1 Sediment Transport Scoping Report – 2013 [Ref 333]
- Cell 1 Regional Coastal Monitoring Programme Walk-over Visual Inspections of Assets 2018 [Ref 401]
- Cell 1 Regional Coastal Monitoring Programme Walkover Inspection Surveys 2018 [Ref 402]
- Full Measures Survey 10 – 2018 [Ref 400]
- Partial Measures Survey 10 – 2018 [Ref 399]
- Cell 1 Regional Coastal Monitoring Programme Aerial Photography and LiDAR Surveys 2017 [Ref 388]
- Cell 1 Strategic Assessment Environmental Report and WFD – 2017 [Ref 385]
- Cell 1 Aerial Survey – 2013 [Ref 335]
- North East Rapid Coastal Zone Assessment (NERCZA) – December 2008 [Ref 218]
- Regulation 28 Report under the Coroners (Investigations) Regulations 2013 – November 2018

Scarborough Borough Council Strategic Coastal Monitoring Programme

- Condition Analysis of Coast Protection Assets Cliffs and Beaches from Staithes to Speeton – July 2005 [Ref 173]

Cell 1 Regional Coastal Monitoring Programme

- *Analytical Report 1 – Full Measures Survey 2008**
- *Update Report 1 – Partial Measures Survey 2009**
- *Analytical Report 2 – Full Measures Survey 2009**
- *Update Report 2 – Partial Measures Survey 2010**
- *Analytical Report 3 – Full Measures Survey 2010**
- *Update Report 3 – Partial Measures Survey 2011**
- *Analytical Report 4 – Full Measures Survey 2011**
- *Update Report 4 – Partial Measures Survey 2012**
- *Analytical Report 5 – Full Measures Survey 2012**
- *Update Report 5 – Partial Measures Survey 2013**
- *Analytical Report 6 – Full Measures Survey 2013**

- *Update Report 6 – Partial Measures Survey 2014**
- *Post Dec 2013 Storm Report – Scarborough**
- *Coast Protection Assets and Coastal Slope Condition Analysis – 2008**
- *Coast Protection Assets and Coastal Slope Condition Analysis – 2009**
- *Coast Protection Assets and Coastal Slope Condition Analysis – 2012**
- *Coast Protection Assets and Coastal Slope Condition Analysis – 2014**
- *Aerial Photographic Survey 2010: Areas of Change**
- *Aerial Photographic Project Report 2012**
- *2012/13 Aerial Survey Analysis Report**
- *Bathymetric and Sea Bed Characterisation Survey**
- *Cell 1 Regional Coastal Monitoring Programme Overview Report (2008-2011)**
- *Wave and Tidal Analysis Report 2013-14**
- *CEFAS Data Report – November 2011**
- *Scarborough Tide Gauge Annual Report 2013**

* available from www.northeastcoastalobservatory.org.uk

Other Cell 1 Coastal Studies

- *Cell 1 Sediment Transport Study – Scoping Report – December 2013 [Ref 333]*
- *Cell 1 Sediment Transport Study – Main Report – July 2014 [Ref 333]*
- *Cell 1 Archaeology Review – January 2014 [Ref 335]*
- *North East Rapid Coastal Zone Assessment – December 2008 [Ref 218]*
- *Cell 1 Inter-tidal Habitat Study - July 2014*